Notice to Mariners № 22 of 2026
BA1138- Jersey East Coast

Petite Anquette Damaged

Mariners are advised that the Petite Anquette beacon, Situtated Anquettes Channel, **49° 08.47' N 001° 56.29' W** has sustained significant damage following Storm Austen.

The beacon should **not be relied upon for navigational purposes**. Mariners navigating in the vicinity of Petite Anquette are advised to exercise caution and to use all available means of navigation.

The future marking of Petite Anquette is currently under review.

A further Notice to Mariners will be issued should there be any change to the navigational marking of Petite Anquette.




Figure 1 Petite Anquette Beacon

Captain Bill Sadler
Harbour Master, Jersey Harbours

30th October 2026