



Notice to Mariners № 06 of 2022

Jersey – Approaches to St Helier

BA Chart 1137

Updated 4 February 2022

Mariners are advised that,

E5 Starboard Lateral Buoy

in position:

49° 10'.71N 002° 07'.17W

Buoy re-instated but remains
UNLIT

This notice will self-cancel when the buoy is back in position and lit

Captain Bill Sadler
Harbour Master, Jersey Harbours

04 February 2022