

Notice to Mariners № 09 of 2024
Chart BA 3655 Jersey South Coast

Frouquier Aubert
Top Mark Missing

Mariners are advised that the top-mark of the Frouquier Aubert South Cardinal Buoy is missing.

Beacon position:

49° 06.08' N 001° 58.88' W

This notice will be cancelled when the top mark is re-instated.



Captain Bill Sadler
Harbour Master, Jersey Harbours

20th April 2024