

Notice to Mariners № 26 of 2023
Jersey's North Coast – BA Chart 1136

Banc Desormes Buoy – TOP MARK MISSING

Mariners are advised that the Banc Desormes West Cardinal Buoy, charted position:

49° 18.9 N 002° 17.9' W

TOP MARK is MISSING

This notice will remain in effect until the top mark has been replaced.



Captain William Sadler
Harbour Master, Jersey Harbours

27 October 2023