

Notice to Mariners № 11 of 2024 Chart BA 1138 Jersey East Coast

Petite Anquette Top Mark Missing

Mariners are advised that the top-mark of the Petit Anquette South Cardinal Mark beacon is missing.

Beacon position:

049° 08.47' N 001° 56.29' W

This notice will be cancelled when the top mark is re-instated.

Captain Bill Sadler

Milling & Sung

Harbour Master, Jersey Harbours

20th April 2024