

Notice to Mariners № 25 of 2024
Chart BA 1137 Approaches to St Helier

Passage Rock Top Mark Missing

Mariners are advised that the top-mark of the Passage Rock North Cardinal Buoy is missing.

Beacon position:

049° 09.540' N 002° 12.262' W

This notice will be cancelled when the top mark is re-instated.



Captain Bill Sadler
Harbour Master, Jersey Harbours

28 August 2024