

Safety Bulletin 04 of 2016

Maintaining Safe Access



Following the recently published [MAIB report](#) in to the death of a line handler onboard the MV Oldenburg in Ilfracombe Masters and Vessel Operators are reminded of their responsibility under the Harbour Regulation (Jersey) 1962 Part 3 to maintain a safe means of access between the ship and the shore at all times when alongside in a Jersey Harbour.

Details of acceptable means of access can be found in Chapter 6 and 18 of the Code of Safe Working Practices for Merchant Seaman and MGN 533.